Weathertzstton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH2696Work Order Type: WeatherizationAudit Name: 13013SH2696

CLIENT INFORMATION

Client ID: 13013SH2696

<u>AGENCY INFORMATION</u>

Client ID: 13013SH2696

Agency: Shelby County Community Services Agency

Agency Phone: (901) 222-4280

Address: 3772 South Hickory Ridge Mall, Suite 516 Fax: (901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact:GAILLARD, GREGWork Phone:Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Measures

M	easure 1 Infilt	ration Redctn			Componer	its			Inspected
Comment Weatherstrip Front, Back and Attic stairs Seal at bathroom sink penetrations Block and Seal A/C wdw#3 Replace broken panes: wdw #5 top (18x25) *remove storm window and reinstall; wdw#10 top (24x27); wdw #9 top (16x27) Glaze top sash wdw #10 Renail facing and caulk wdw #8 Caulk & glaze wdw #7 Caulk facing at bottom of wdw #2 Replace facing entire wdw #4 Replace sill wdw #6 Replace crawl space door (21x16)									
					Estimated	<u> </u>		Actual	
# /	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 [Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
Otl	her Detail						_		
				Measur	e Sub Total:			Sub Total:	
F	ield Notes:								

	Measure 2 Repl	ace A/C			Componen	ts AC1			Inspected	
C	Comment Replace	Central A/C system -cor	mplete 3	Γon						
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Cooling Equipmen	Central A/C -	Each	1						
2	Labor	Central A/C -	Each	1						
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
		I Pipe Insulation ater lines (hot and cold) 1	O ft		Componen	ts		,	Inspected	
		-	0 ft		Componen Estimated			Actual	Inspected	
C		-	0 ft <i>Unit</i> s	Qty	•		Qty		Inspected	
C	Comment Wrap wa	ater lines (hot and cold) 1			Estimated		Qty	Actual		
C # 1	Comment Wrap was	ater lines (hot and cold) 1 Description / Comment	Units	Qty	Estimated		Qty	Actual		
C # 1	Comment Wrap was Material / Labor Insulation	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual		
C # 1	Comment Wrap was Material / Labor Insulation Labor	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual		
C # 1	Comment Wrap was Material / Labor Insulation Labor	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual		
C # 1	Comment Wrap was Material / Labor Insulation Labor	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated			Actual		
C # 1	Comment Wrap was Material / Labor Insulation Labor	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost		
C # 1	Material / Labor Insulation Labor Other Detail	ater lines (hot and cold) 1 Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost		

Measure 4 Floo Comment 850 sq f				Componen	ts F1			Inspected
Comment 000 3q 1	. 10 10			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	850					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	850					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Measure 5 CO N	Monitor is Needed			Componen				Inspected
Comment Qty 1		Unito		Estimated			Actual	
Comment Qty 1 # Material / Labor	Description / Comment	Units Fach	Qty 1	-		Qty		Inspected Total
Comment Qty 1	Description / Comment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment Qty 1# Material / Labor1 Health and Safety	Description / Comment		_	Estimated		Qty	Actual	
Comment Qty 1# Material / Labor1 Health and Safety	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
Comment Qty 1# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
Comment Qty 1# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
Comment Qty 1# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	1	Estimated			Actual	
Comment Qty 1# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Health and Safety 2 Labor Other Detail	Description / Comment CO monitor	Each	1	Estimated Unit Cost			Actual Unit Cost	

	Measure 6 Fix II	mproper Venting (Clot	hes Dryer) (Compone	nts			Inspected
C	Comment Replace	dryer vent & cap -comp	lete						
					Estimate	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Fix Improper Venting	Each	1					
2	Labor	Fix Improper Venting	Each	1					
(Other Detail								
L									
				Measure	Sub Total:			Sub Total:	
	(Bas	or Barrier Needed ement/Crawlspace) ound cover 850 sq ft		(Compone				Inspected
#	Material / Labor	Description / Comment	Units	Qty	Estimate Unit Cost	Total	Qty	Actual Unit Cost	Total
1		Basement / crawlspace vapor barrier	SqFt	850	Omi Cost	Total	Qiy		Total
2	Labor	Basement / crawlspace vapor barrier	SqFt	850					
(Other Detail								
L									
				Measure	Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	der Gran	nd Total:		Gran	d Total:	